

Tween decks.

# MONTREAL OFFICE

CLAYTON

Report No. Mtl. 12811

Name:-

Nature of Survey:-

DAMAGE SURVEY

Damage stated caused by grounding on 29th April, 1959.

The following remains to complete the survey:- As the vessel was in drydock the Owners took the opportunity to commence a Lake Special Survey. In view of the extensive repairs necessary however they decided to lay the vessel up and she proceeded to her lay-up port Port Colborne

Recommendations:-

The vessel appears eligible to remain as classed (without) fresh record if it is submitted action be deferred.

Insert in S.R.L.

vessel to be drydocked & repairs effected as necessary before recommissioning.



© 2020

Lloyd's Register  
Foundation

July 22nd, 1959

002897-002906-0006