

The class is subject to the main engine first MP cylinder being examined by 1.60.

4E

16 SEP 1959

ived by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....


P'S NAME EASTMAN.....

REPORT Col.....

No. 4457.....

The Surveyor reports some repairs effected to the main condenser.

IT IS SUBMITTED that this vessel is eligible to remain as CLASSED, subject as above.



16.9.59.

© 2020



Lloyd's Register Foundation

002897-002906-0081