

P'S NAME "AVLIS" REPORT Pir No. 9401

GB

standing Conditions of Class: SUBJECT to indented shell plates A.2, B.2, C.2 & 3 and D.2 (p.s.) also A.1, B.1, C.2, D.3 & E.3 (s.s.) and to shell rivets in bilge keel (p & s) being examined and dealt with as necessary at the next drydocking.

ACTION is DEFERRED for Repairs.

L. Appendix. (As before ~~or None~~)

veys due: SPECIAL SURVEY (C) due 11,61. The Owners' proposal to postpone same for 12 months was approved subject to a G.E. being held in dry dock at Pir.7,61. The G.E. commenced Piraeus 7,61 by the examination of the ship in dry dock.

ure of Present Survey: (Afloat and in dry dock)

Deferred repairs to extensive H.W. and contact damage.

cial Features:Interim Certificate in order (Yes-~~No~~-None)ns Outstanding: (If any for S.S.)

ALL ITEMS.

ITEMS FOR G.E.:- All items EXCEPT Drydocking.to be completed by:ommendation:

SUBJECT as above, and to damaged rudder, sternfrane, bow plating etc. (p & s) being dealt with before ship is re-commissioned, but ACTION continue to be DEFERRED for Repairs.

and for S.S.

SUBJECT

IN S.R.L. APPENDIX.

Shell plates G.9 and H.9 (s.s.) indented.
Boat and poop deck guard rails (p.s.) buckled.



© 2020

Lloyd's Register
Foundation

002897-002906-0132