

COPY

LLOYD'S REGISTER OF SHIPPING



Port of Oslo

14th April, 1962.

This is to Certify that I have

Surveyed the Machinery of the motor ship "BRALANTA" 9608 tons

gross, of Oslo, for ABS, and advancement of CS, whilst in dry dock and afloat at Sandefjord

and that I will transmit to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction; also that I will Recommend that in the case of this Vessel the following Survey Records be made in the Supplement to the Register Book

ABS 4/62 and CS, with date when survey completed and that her Machinery Classification Record be continued in the Book,

subject to starboard boiler slightly set in, inboard furnace lower half being specially examined next Boiler Survey.

Parts now examined:

(C.S. Items only)

M.E. No. 1 crankpin and bearing and top end and bearings.

S.S. Forward auxiliary engine throughout.

Machinery under working conditions.

Engineer Surveyor to Lloyd's Register

KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey
CS Continuous Survey of Engines
DBS Donkey Boiler Survey
ES Engine Special Survey
MBS Main Boiler Survey
MES Modified Survey of Oil Engines
OF Fitted for oil fuel (date) FP above 150°F.

SGS Steam Generator Survey
SPS Steampipe Survey
TS Tailshaft Survey
TS(CL) Tailshaft Survey—Continuous Liner
TSN Tailshaft renewed
TS(OG) Tailshaft Survey—Oil Gland

L. Tveit

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B.1.) 150m,5,60 (MADE AND PRINTED IN ENGLAND)

002897-002906-0258