

Chief Engineer Surveyor _____

Received from Chief Engineer Surveyor _____

NAME Bralanta Rpt. Malua No. 1495

s of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. —Extract from Sub-Committee's Report, 24/5/92.)

of Engine

Oil Engine2 S.C. D.A7. cy. 23 5/8" - 43 5/16"H.M.P. 1358~~If Boilers fitted with forced draught~~

Tail Shaft. If fitted with a continuous liner

yes

If fitted with an outside gland of }
approved type

no

This vessel's machinery appears to have been built in accordance
the Rules and the approved plans, and it is submitted she is
ble to be classed

+ L.M.C. 9.362 D.B. 1701b.1 DB (W.T.B) 1701b.Yam6.10.36

© 2020

Lloyd's Register
Foundation

002897-002906-0269