

COPY.

Hamburg Report No. 21828

Lloyd's Register of Shipping.



Port of Hamburg.

11th March, 1936.

This is to Certify that

XXXXXXXXXX Heinrich Schneider XXXXXXXXXXXXX

the undersigned Surveyor to this Society did at the request of Messrs. Deutsche Werft A.G., Hamburg, attend at their works on the 25th February, 1936, and subsequent dates, for the purpose of examining and testing during construction one Waste Heat La Mont Donkey Boiler, consisting of headers, heating coils and covering plates, to the order of Messrs. Kockuss Mek. Verkstads A.B., of Malmö, and intended for their construction No. 191., now being built.

The Waste Heat La Mont Donkey Boiler has been constructed to the scantlings and dimensions as given on the approved plan and letters thereto and the material used in the construction has been made at approved works and tested by the Society's Surveyors in accordance with the requirements of the Rules with satisfactory results.

The Waste Heat La Mont Donkey Boiler has been tested in my presence on the 3rd. March, 1936, by hydraulic pressure to 21,5 Kgs. per square cm., and showed no signs of weakness and was found tight and sound in every respect at that pressure.

Working pressure not to exceed twelve Kgs/cm².

The workmanship was found satisfactory. For identification purpose the donkey boiler has been marked as follows:-

No. 611.

Lloyd's Test.
21,5 Kgs/cm².
W.P. 12,0 " " "
H.S. 3-3-1935.

W. Schneider
SURVEYOR TO LLOYD'S REGISTER.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."