

5c11.44.

Blythwood S.B. Co. Ltd., Glasgow.Yard No.80.

1

CAMILLO

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME "EMPIRE TRINIDAD" REPORT Gls. No.70044

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey First Entry

WATER

Two longitudinal bulkheads are fitted.

1100A1 "Carrying Petroleum in bulk"

11.45 Gls.

1 Dk "Longitudinal framing at bottom and at deck"
"Pt. electrically welded"

Cell DBUE 70' 42t, DTf 23' 287t, FPT 150t, APT 87t.

FK, 16 BH, Lloyd's A & CP


P 92; B 51', F 49'

Mchy Aft

O.L. 484.0'


E.S.D.

cf



The class is assigned and maintained upon the understanding that the equipment will be made to accord with the requirements of the Rules when the present state of emergency has passed.

Insert/in S.R.L:- (A bower anchor and 60 fathoms of chain cable to be supplied).



10.1.46

2021

Lloyd's Register
Foundation

002907-002915-01SS