

4E


to the exhaust gas economiser not being used.

29 JAN 1960

Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....
 AME..... RIO BESAYA..... REPORT Vca..... No. 1050

The Surveyor reports the main and auxiliary machinery generally examined under working conditions in accordance with the instructions contained in the Society's letter dated 2nd December, 1959.

IT IS SUBMITTED this vessel is eligible to remain as classed, subject as above.


 26.1.60.



© 2021

Lloyd's Register
 Foundation

002901-002915-0221