

COPY.
PORT OF GLASGOW

GLASGOW REPORT No. 52440

LLOYD'S REGISTER OF SHIPPING,
201, TOWER BUILDING,
LIVERPOOL.

12th May, 1932.

Dear Sir,

I beg to advise you that 135 fms. of new cable have been connected to the anchors of the New Ferry Boat "ROYAL IRIS II", starboard cable lifter renewed and windlass tried and found satisfactory. A new starboard warping drum requires to be fitted, the original having been broken during removal of cable lifter. It is understood that 45 fms. of new cable remains to be supplied, to replace three of original lengths still in place.

In addition to above, the valves in engine room connected to fore and aft peak tanks have been made non-return as required.

The above items will be officially reported in due course.

Yours faithfully,

(Sgd.) J.E. MILTON.

The Secretary,
GLASGOW.



© 2021

Lloyd's Register
Foundation

002907-002915-0274