

Was a damage report made by anyone else? If so, by whom?

Im.11.36.

fees paid

Received from Chief Surveyors

Chief Surveyors *17. 2. 37*

VESSEL'S NAME

SH Ss DENBIGH COAST

Report

Li

No. *108446*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Examination of hold & close stowage when due

Bottom of vessel in motor space to be specially examined internally when in dry dock.

W.H.B.

17 Feb 1923

Delete "Largo ballers not fitted."



© 2020

Lloyd's Register
Foundation

002923-002928-0201

(state if examined.)

Standing and Running R

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book without fresh award of Survey "to remain as classed and notified."