

December 6, 1938.

S.S. "JOHN B. RICHARDS"

Freeboards same as provisionally assigned.

It is noted that the hatch beams have been reinforced to Rule standard.

Panel door (inner) to be replaced by steel doors at engine room entrance.

Closing arrangements for air pipes to be supplied where necessary.



© 2021

Lloyd's Register  
Foundation