

31st May, 1960

HAMPTON

51, 87, 125, 49, 50, 68 - As recommended.

53 "ATHLONE CASTLE" - As recommended, except that no notations in respect of the hull and machinery Special Survey have been assigned this time. To complete the present CS cycle of the machinery, the pumps of the oil installation, the evaporator (if fitted) and the auxiliary air receivers still remain to be examined, and the Owners being requested to make arrangements for these items to receive attention at an early date.

59 "DILWARA" - As recommended, except that the 30 fathoms of chain should be renewed at the earliest opportunity.

58 "EDINBURGH CASTLE" - As recommended, except that the class has been continued subject to shell plating (port and starboard) being specially examined and dealt with as necessary at the next drydocking, and to plating (port and starboard) being specially examined and dealt with as necessary by completion of the Special Survey and as previously ordered.

61 "ISLE OF SARK" - As recommended. I shall be glad to learn what arrangements the Owners propose to make to complete the Special Survey.



© 2020

Lloyd's Register
Foundation

002938-002946-0048