

27 MAY 1960

Received from Chief Ship Surveyor.....

SHIP'S NAME "ISLE OF SARK" REPORT SOU No. 26161

Outstanding Conditions of Class: SUBJECT to indented side shell plating (p.s) being specially examined and dealt with as necessary next Special Survey, and to indented 'B' strake plate No.9 (s.s) being specially examined and dealt with as necessary by completion of the Special Survey.

R.L. Appendix. (~~As before~~ or None)

Surveys due: SPECIAL SURVEY (C) due 4,60 - commenced 1,60.

Location of Present Survey: (Afloat ~~and in dry dock~~)

Advancement of S.S. Temporary repairs to stem and stem plating and shell plates G.6 & 7 and H.7 (s.s. from aft) on account of contact damage.

Special Features:

Interim Certificate in order (Yes ~~No~~ None)

Items Outstanding: (~~if any for S.S.~~)

FOR PORTION OF SURVEY HELD:- See this report. ?

S. to be completed by:

Recommendation: SUBJECT as above and to Buckled stem and stem plating and set in shell plates G.6 & 7 and H.7 (s.s. from aft) being specially examined and dealt with as necessary by completion of the Special Survey.

As Now SUBJECT

the Sou.
Write Owners ~~en~~ S.S. PART HELD. inquiring when and where they propose completing S.S.



© 2020

Lloyd's Register
Foundation