



LLOYD'S REGISTER OF SHIPPING

Cato House, 340, Smith Street, Durban

Telegrams: Lloydsreg

P.O. Box 170

Telephone: 2-4092

A I R M A I L

28th April, 1961.

Your Ref: Classn.(S)

RECEIVED

4 - MAY 1961

Ans'd

Mr Sir,

"IRISBANK"

Drb. Rpt. No. 9211

In reply to your letter of the 21st instant, I have to inform that I did not examine the flexible coupling which was fitted, under working conditions.

On completion of repairs I attended the ship with a view to seeing this done but found that some minor adjustments were being made, the Chief Engineer stating that a satisfactory test had been carried out. I am afraid I accepted his statement and did not make a further visit to the ship.

In future cases I will make a point of personally witnessing a

Yours faithfully,

P. F. Balfour

P. F. BALFOUR.
FOR THE SURVEYORS.

Secretary,
DON.



© 2020

Lloyd's Register
Foundation

002438-00246-0060

保

H 100

25/5/61

© 2020

Lloyd's Register
Foundation