

name "BRITISH CAPTAIN"

Port GLS.

No. 93876

Last survey date 30.8.62.

is subject to

NIL.

Temporary repairs effected to M.E. tie rod between No's 5 and 6 units and the Surveyor recommends that the M.E. tie rod between No's 5 and 6 units, Port side being specially examined and dealt with as necessary before the end of September 1962.

It is submitted that this vessel is eligible to remain as **CLASSED.**

Subject as now recommended,



© 2020

Lloyd's Register
Foundation

APL
25.9.62

CS(M)

See Form 7E.

007938-002966-0163