

129 OCT 1933

s.s. "SALVADOR".

London 99188a.

The examination of the screwshaft became due in 6,33.

From information received through the Buenos Aires the Owners state that they do not desire to retain the vessel's class in this Society, and that no arrangements have been made for examination of the vessel's screwshaft.

IT IS SUBMITTED the vessel's class be expunged from the Register Book and three dots (...) be inserted in lieu thereof, indicating withdrawal of class at Owners' request.

Withdraw class.

Insert ...

29.9.33.



© 2020

Lloyd's Register  
Foundation

002938-002946-0220