

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

Rpt.

No.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	20'	Proportions
Spar Sheerstrake . .	✓	✓
Description of Framing:—Single angle, increased to compound (viz., ordinary, deep, zed, channel or bulb-angle). For omission of cross frames.		

The Machinery has been fitted at Glasgow & the Surveyors report that the engine & boiler casings have been riveted up.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ± 100 A.1. (Std) as recommended.

± 100 A.1. (Std)

1 St. (std)

"Wul dur"

FK. B.H. Gen Lloyd's at 60, 249 B J F 28 'Mch' APL

W.B. F.P.T. J.L. A.P.T. 26

Lloyd's Register
Foundation

002938-00946-0322

Forecastle Deck Stringer Plate, breadth & thickness

Angle on ditto