

Lord Beaconsfield

F.E.

Received by Chief Ship Surveyor 12-10-15.Received from Chief Ship Surveyor InsVESSEL'S NAME Steel SS TribuneRpt. Ins10109.  
No. 2886

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 36-45Depth "d" 11.75Framing: Table No. 3 page 9Description Single Angle as approved.Longitudinal No. 4920Proportions  $\frac{\text{Length}}{\text{Depth}} = \frac{10.3}{11.75}$ ~~Deck~~ Sheerstrake -56 of an inch instead -38 as reqd.

*The vessel has been examined in dry dock & the  
bottom cleaned & coated.*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed  $\star$  100A-1. (Steel) Steam Trawler, as recommended.

 $\star$  100A-1. (Steel) Steam Trawler.

1 BK.

BK 7 $\frac{1}{2}$ . 48H. "Cin" Legs as exp. Q 74. F 21.

*The surveyor should be requested to forward  
the foregoing reports.*



© 2020

Lloyd's Register  
Foundation

002942-002955-0020