

Ship's name

ST. EVAN

WRECK
SECTION

No. 14319

Class is subject to NIL.

No. ~~14319~~

Last survey date 19/9/62

Docking

MBS due 9.62, now partly heeled

the Surveyors reports star fractures $1\frac{1}{2}$ " to 2" in length on bottom shell plate of the main boiler radiating from two lower rows of the wing combustion chamber wrapper plate stays. No repairs effected.

The M/E # P cylinder fractured vertically on p. 5. 24" long.

The Owners state tug now sold for breaking and the notation "To be broken up" entered against the ships name in the R.B.



2020
11/1/63

Lloyd's Register
Foundation