

Received by Chief Ship Surveyor

13/6/10

Received from Chief Ship Surveyor

VESSEL'S NAME

M S tug Danube II

Rpt.

Ply

No.

536

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

First entry

It is submitted that before this case receives the consideration of the Committee, the Hull Surveyors should be informed that in order to complete the survey on the hull of this vessel the Plymouth Surveyor states that the boiler casing top requires to be riveted up after the boiler is shipped.

Rr. Hul. 13.6.10



© 2020

Lloyd's Register
Foundation

002947-002955-0061