

by Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME

7/6/10  
*St. Aug Danube II* Rpt. *Ply*

No. *2306*

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

f Survey

*First entry*

It is submitted that before this case reaches the consideration of the Committee the Hull Surveyor should be informed that this vessel has been towed to this port where her machinery is to be fitted. They should be requested to give the case the necessary attention on completion of the work to forward a report on form 8 with a view to the classification of the vessel.

The Plymouth Surveyor should be requested to state what work remains to be done to the hull of the vessel, in view of the machinery being fitted at Hull & at the same time he should state the statutory breaking test of the chain cables.

*As Hull & Ply.*  
*7/6/10.*



*2306*  
© 2020

Lloyd's Register  
Foundation

202947-002955-0063