

AUGUSTE R. BERG

Tw. Sc. M.S. "WASHINGTON EXPRESS"

THE attached letter has been received from the
Gothenburg Surveyors from which it would appear that the particulars
of water ballast supplied by the Builders and given in their first
entry report No.9514 are ^{not} ~~is~~ incorrect.

In these circumstances the particulars of Water
Ballast in the Register Book, viz:-

Cell DB uE & f 158' 370t, D.Ts. a 677t, FPT 34t, APT 59t
should be amended to

Cell DB uE & f 158' 427t, D.Ts. a695 t, FPT 35t, APT 60t

HP.
Jus

18.1.34.



© 2020

Lloyd's Register
Foundation

002947-002955-0074