

5m 9,60

✓ aft Weir feed-pump water-valve (Metlock 2/59) being examined
by 1/61

4E

Cass is subject to 2 Repairs to fracture in fabricated A-frames between Starboard
Outer Main engine NO. 3 and scavenge pump being specially examined
by 3/61 (12 months limit). (Imposed 2/59).

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

SHIP'S NAME M.V. DOMINION

MONARCH

REPORT

London

No. 143801

A.B.S. due 1/61, partly held 10/60, not advanced.
C.S. advanced.

30 NOV 1960

It is submitted that the
vessel WILL BE eligible
for the record A.B.S. 10/60
when the survey has been
completed, under this Rft, Subject as above.

W.C.
29/11/60.



© 2020

Lloyd's Register
Foundation

002947-002955-0166