


COPY

# LLOYD'S REGISTER OF SHIPPING

W. Akel  
12-62

13 NOV 1960



Port LONDON

7th November, 1960.

WRECK  
SECTION  
No 789

Parad 1

This is to Certify that I have

Surveyed the Machinery of the M.V. "DOMINION MONARCH" 26463  
tons gross of Southampton whilst afloat in this port for  
Advancement of CS and advancement of ABS

and that I will transmit to the Committee of Lloyd's Register of  
Shipping, London, a Report stating that all recommendations made by  
me in connection therewith have been carried out to my satisfaction; also  
that I will Recommend that in the case of this Vessel the following  
Survey Records be made in the Supplement to the Register Book  
CS (with date) when the survey has been completed, ABS 10.60.  
as previously recommended when the port oil fired and stbd  
waste heat boilers have been examined in their entirety with  
safety valves and mountings and their safety devices tested under  
and that her Machinery Classification Record be continued in the Book  
subject to any outstanding conditions of class being dealt  
with as previously recommended.

Parts now examined:

(C.S. Items only)

- Independent starboard main lubricating oil pump
- Independent centre piston and jacket C.W. pump
- Independent emergency fire and bilge pump
- Independent starboard (outboard) C.F. transfer pump
- Independent starboard main and emergency (petrol driven)  
air compressors, coolers and safety devices.
- Forward evaporator safety valves adjusted under steam to  
15lbs/sq.in.
- Port steering gear pressure pump

*W.G. Brown*

Engineer Surveyor to Lloyd's Register

W.G. BROWN.


KEY TO ABBREVIATIONS

- ABS Auxiliary Boiler Survey
- CS Continuous Survey of Engines
- DBS Donkey Boiler Survey
- ES Engine Special Survey
- MBS Main Boiler Survey
- MES Modified Survey of Oil Engines
- OF Fitted for oil fuel (date) FP above 150°F.

- SGS Steam Generator Survey
- SPS Steampipe Survey
- TS Tailshaft Survey
- TS(CL) Tailshaft Survey—Continuous Liner
- TSN Tailshaft renewed
- TS(OG) Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—  
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed,  
it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held  
responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book  
or other publication of the Society or for any error of judgment, default or negligence of any of its Committees or any Member thereof,  
or the Surveyors, or other Officers or Agents of the Society."

(Cert. B.1.) 150m,5,60 (MADE AND PRINTED IN ENGLAND)



© 2020

Lloyd's Register  
Foundation

00947-002955-0167  
551500-747200