

## LOYD'S REGISTER OF SHIPPING

Port

London

3rd May, 1962.

This is to Certify that I have

and the Machinery of the

S.S. M.V. "DOMINION ROYAL" 26463  
 of Southampton, for CG, completion of ABS, and  
 of Class in respect of (1) "Metalock" repairs to the  
 Weir feed pump water end, (2) repairs to fracture in the  
 and will transmit to the Committee of Lloyd's Register of P.T.O.


London, a Report stating that all recommendations made by  
 in connection therewith have been carried out to my satisfaction; also  
 will Recommend that in the case of this Vessel the following  
 Records be made in the Supplement to the Register Book  
 (date) when the survey has been completed and ABS  
 as previously recommended.

her Machinery Classification Record be continued in the Book.

to the "Metalock" repairs to the after Weir feed pump  
 and being again specially examined by the end of December,  
 repairs to the fracture in the fabricated 'A' frame between  
 starboard Outer Main Engine No. 3 unit and scavenge pump  
examined: crankcase being again specially examined by the  
 (ends only) end of December, 1962 the starboard Main Air  
 Compressor entablature block being again  
 specially examined by the end of December, 1962 and the port  
 Generator Engine "Metalock" repair being again specially  
 examined by the end of December, 1962. subject to any other out-  
 going conditions of class being dealt with as previously recom-  
 mended.

Now Examined:

diesel generator auxiliary engine in its entirety.  
 arrangements examined and tested.



Engineer Surveyor to Lloyd's Register

## KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey  
 CS Continuous Survey of Engines  
 DBS Donkey Boiler Survey  
 ES Engine Special Survey  
 MB Main Boiler Survey  
 MES Modified Survey of Oil Engines  
 OF Fitted for oil fuel (date) FP above 150°F.


SGS Steam Generator Survey  
 SPS Steampipe Survey  
 TS Tailshaft Survey  
 TS(CL) Tailshaft Survey—Continuous Liner  
 TSN Tailshaft renewed  
 TS(OG) Tailshaft Survey—Oil Gland

R.C.R. MIDFORD.

is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed,  
 understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held  
 any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book  
 tion of the Society or for any error of judgment, default or negligence of any of its Committees or any Member thereof,  
 or other Officers or Agents of the Society."

m.5.60 (MADE AND PRINTED IN ENGLAND)



© 2020

Lloyd's Register  
Foundation

002947-002955-0199