

F.E.

Received by Chief Ship Surveyor

31.8.14

Received from Chief Ship Surveyor

VESSEL'S NAME

M. S. S. Donaldson

Rpt.

Hal

No.

27860

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

35.41

Depth "d"

11.25

Framing: Table No.

3 page 10

Description

Longitudinal No.

4143

Proportions

Length

Depth =

8.6

Deck Sheerstrake

.56 of an inch instead

of .34 as required.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed $\frac{1}{2}$ 100 A. 1. (Steel) "Steam Trawler," as recommended.

$\frac{1}{2}$ 100 A. 1. (Steel) "Steam Trawler."

1 SR.

BH. $7\frac{1}{2}$ 4 BH. Com Lloyd at 61 Q61

M



© 2020

Lloyd's Register Foundation