

22nd Sept.

19 47

ard (if assigned) as } 10
ip and now verified }

5m.10.47.

mn

1

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

L'S NAME CLAN ALPINE REPORT Gls. No. 72302

For the CHIEF SHIP SURVEYOR ~~AND CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24 /5/92.)

Survey..... When due.....

letroom

The class is subject to indented shell plates (p.s) being dealt with at the first convenient opportunity.

The Owners' proposal to leave off the bolted plates over the tonnage opening in the 'tween deck bulkhead at Frame 93 has been approved - see endorsement 10.5.48.

This alteration affects the vessel's present record in the Register Book.

It is submitted the vessel's class be continued, subject as above.

As Now, subject.

Amend R.B:

From 5 divisional WT BHS in 'tween dks
To 4 divisional WT BHS in 'tween dks



2020
20.5.48
[Signature]

002956-002969-0079

To the Surveyors,
Lloyd's Register of Shipping,

6/11/48

Lloyd's Register
Foundation

Conversion
lined and
ling under
tanks
tanks tested
Month
&c.
ascertained by
(ages removed.)
er
38.
now ranged)
270 mean d
(board.)
270
gth 270
ARPS
unning Rigging