

Steering Chains (Size and Test)

Selenator ✓

Windlass Lucas Selsker

ness, material

Hatches

o. 5 35

BEHALF OF THOMPSON

R.C.S.

ning of oil  
in which oil

Secret

to see

record

tips

id and

stamp

same

Ms. 318.

(Received at London Office,.....)

o. 1. 5985 Port Sunderland. Date May 7<sup>th</sup> 1941.

We request that the Single screw steamer Building  
Ministry of Shipping, by Joseph L Thompson Sons Ltd  
7800 Tons. Length, 416.0 breadth, 56.10 1/2 depth, 37.4

to be Specially Surveyed while building ( 100. A.1. ) If for a particular term or class, state the same.

We hereby engage to pay the established Special Survey Fees as set forth in the Society's Rules, and, in addition, any travelling and other expenses which may be incurred by the Surveyors in connexion with the survey.

In no case can the vessel be classed until all fees, travelling expenses, &c., due thereon are paid.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping, which provide that:—

“While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member hereof, or the Surveyors, or other Officers or Agents of the Society.”

No. 615 in Builder's Yard. Manufacturers of Engines George Blanks (1938) Ltd

Old Auth. 13.5.41

Ditto of Boilers JOSEPH L THOMPSON & SONS, LIMITED. Signature R. N. Thompson.

To the Secretary, Lloyd's Register of Shipping, 71, Fenchurch Street, London, E.C.3.

© 2020 Lloyd's Register Foundation Chairman

002956-002969-0091