

Surveyed Afloat or in Dry Dock? *Both*. Name of Dockmaster *John*. Destined Voyage *to*
 WB=Cell ~~DBa~~ DBa 50 feet; uE&B *✓* feet; f *✓* feet }
 72 tons EPT 105 tons APT 115 tons MT *✓* feet *✓* tons.

Particulars of Classification (which precisely as in Register Book & ...)

WRECK
SECTION
No. 711
Received by Chief Ship Surveyor

Subject to indented plating being dealt with at
 & owner's convenience.

27 NOV 1930 1

Received from Chief Ship Surveyor
 VESSEL'S NAME *St. Sc. "AUGUSTA. L."* Rpt. *Bgn* No. *2133*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

re of Survey DAMAGE.

M. ALICE

FREYMAN

Damage through *grounding*.

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed	13			10			
Removed and faired or repaired.....	12	10		23	1		
Faired or repaired in place.....	50	46	13	20	5		

Other items:-

Vessel placed in dry dock, repairs effected to stem, centre & side keelsons, intercostals, tank margins, tank side brackets, bulkheads & minor repairs carried out.

Bottom coated.

Wear & tear:- 1 shell plate renewed & 2 repaired, tank tops in fore peak & after hold repaired & minor repairs effected.

It is submitted the vessel is worthy to remain as classed with

record of Survey 11.30 *Subject to F. 9. Starb-Side being faired at as recommended. The owner's convenience, but without other condition.*

100 A.1
11.30 Bgn

The Certificate of Classification to be endorsed "Cargo buttons not fitted" and the same notation to be entered in the Register Book.

27.11.30

It should be pointed out to the Surveyor that in all future cases he should state in the space provided on Report form 8, for that purpose, under the heading "Summary of Damage Repairs" the number of shell plates re, renewed or repaired.

subject to F. No 9 St.B. being faired at owner's convenience.

002956-002969-0189

signed) as
verified
derwriters
September
ically
t. No 8
in pla
W
M. of Wood
on Felt.
on, Month
&c.
w ascertained
if wedges ren
letter
of
e if now ran
board)
ngth
Varps
l Running Rig
gister Book
lassed and t
ent co
survey