

Grounding damage T.S. found defective
now renewed. Shafting excd &
re aligned

N.B.—If this Report is copied by copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

B.S. due 6. 30 now held

It is submitted that
this vessel is eligible for
THE RECORD B.S. 11. 30

S. 11. 30 (N)

Y. Kan
27. 11. 30

doors and fastenings examined. Uptake of boiler cropped and partly renewed at
bottom.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2020

Lloyd's Register
Foundation