

COPY

LLOYD'S REGISTER OF SHIPPING

Port Liverpool.17. 2. 59.

This is to Certify that I have

part

Surveyed the Machinery of the S.S. "TROCHISCUS" 10685 tons gross
of London whilst afloat and in drydock at Birkenhead for Boiler &
Machinery surveys and Electrical Repairs,

and that I will transmit to the Committee of Lloyd's Register of
Shipping, London, a Report stating that all recommendations made by
me in connection therewith have been carried out to my satisfaction; also
that I will Recommend that in the case of this Vessel the following
Survey Records be made in the Supplement to the Register Book

M.B.S. 1,59

and that her Machinery Classification Record be continued in the Book.
subject to the new section of coils fitted in the main propulsion motor
stator, and the repaired section of the slot laminations being specially
examined and dealt with as found necessary at the next drydocking, by the
end of January, 1960 (12 months limit) and the temperature detector being
fitted in the bottom section of the stator winding also by the next drydocking


Parts now examined: Jan. 1960 (12 months limit).

(C.S. Items only)

Propeller and outside fastenings.
Both turbo feed pumps.
Aux. extraction pump.
Starboard main extraction pump.
Inboard turbo-generator turbine, gears & oil cooler.
Outboard main lub. oil cooler.
Aft Butterworth pump.
Port F.D. fan & both distillers.

Inboard Alternator, main exciter, pilot exciter and amplidyne unit.
Inboard main condensate pump. Port F.D. Fan Motor. Main Propulsion alternator.

(J. BOWMAN).


Engineer Surveyor to Lloyd's Register

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Cert. B.1.) 50m,3,58 (MADE AND PRINTED IN ENGLAND.)

002956-002969-0238

© 2020

Lloyd's Register
Foundation