

Sterntube Lloyds F.N.B. 414 18-11-30
Screwshaft " M.K. 3406 14-5-30
Intermediate shaft " F.S. 146 18-11-29

2c.11.30.

1E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

Yfisadane

Rpt.

Ans

No.

12326

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine

oil Equies 2 S.C. S.A.

If Boilers fitted with forced draught

no Boilers

Tail Shaft. If fitted with a continuous liner

Yes


If fitted with an outside gland of

no

approved type

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

+ LMC 6.31



It is concluded that the Hull spare gear for the Auxiliary Engines has been supplied but this should be confirmed.

on 17/7

Mr. Reck 20/7/37

© 2020

Lloyd's Register Foundation

002970-002977-0013

002970-002977-0014 1/2

F.N.B. 307 19-7-30
F.N.B. 1 5-8-30