

COPY

+LMC 2

BS 1

OG. 1

Received from Chief Ship Surveyor **110 FEB 1959**

SHIP'S NAME

"TUDOR QUEEN"

REPORT

Gms.

No. 27748

Outstanding Conditions of Class:

Subject to set up bottom shell plate

B.3 (p.s.f.) being dealt with as necessary at next drydocking.

Endorsement of Certificate (~~As before~~ or None)

Signature of Present Survey: (Afloat and in dry dock)

Drydocking: Repairs to shell plating on account of contact, grounding and ranging damages including repairs to the deferred item above: Minor wear and tear repairs.

Recommendation:

SUBMITTED record of 'DS 1,59' be assigned, but without special condition.

DS 1,59 Without.

Blk(new)



© 2020

Lloyd's Register
Foundation

002970-002977-0035

Record. Queenship Navigation Ltd.,
Superintending Engineers Dept.,

ent to