

4E

Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

3 MAY 1957

1E "KUURTANES"

REPORT Cpn

No. 16274

Docking. Screwshaft seen and now changed.  
The shaft now fitted has been repaired  
and the Surveyor recommends that the  
screwshaft be renewed before the end of  
9.57 (TS record withheld meantime).

IT IS SUBMITTED that this vessel is  
eligible to remain as classed, subject as recommended.

*W. Allen*  
2.5.57.



©

2024

Lloyd's Register  
Foundation

002970-002977-0075