

Total
Gross Tonnage 420.55
Register Tonnage 167.61

Depth, at middle of length from top of keel to top of beam at side of uppermost continuous deck. See Sec. 3 (1c) } D 14'-6"
1st Longitudinal Number (L x D)..... = 2199

Owners *Hudson Steam Co. Ltd.*
Managers *✓*

5c.7.31.

Mr. Loden

~~Carter~~ CARELLA
EX

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *SS S. CAPE BATHURST* Rpt. *Hul* No. *43937*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

10' Long

Transverse No. *2199*

Depth "d" *✓*

Framing: Table No. *✓*

Description *Angle frames as approved*

2nd Longitudinal No. *6066*

Proportions $\frac{\text{Length}}{\text{Depth}} = 10.4$

Deck Sheerstrake *As approved*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100A1 (Steel) Steam Trawler

1 DK.

B.K. $7\frac{1}{2}$ H.B.H. Cen. Lloyds A + C.P.

Q 81' F 23'

3-8-33

3-8-33

© 2020



Lloyd's Register Foundation

002970-002977-0168

" " Angle

Poop Deck, Angle, E or F

Spacing