

ACTION is DEFERRED for examination in dry dock after grounding.

Surveyors.....

Received from Chief Surveyors.....

NAME "C H A R O" REPORT S Gal. No. 6619  
Mob. " 3093

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92).

Survey. Permanent repairs to damage ~~when due~~  
caused by heavy weather.

N O T E D.

ACTION is DEFERRED for examination in dry dock after grounding.

IN S.R.L.  
Drydocking(grounding).

IN S.R.L. APPENDIX.  
Indents in shell plating (s.s.f).

CBM.  
29.4.59



© 2020

Lloyd's Register  
Foundation

002989-002996-0008