

Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

NAME CEDAR POOL

REPORT

No.

To enable the vessel to proceed to an Italian port  
the following parts should be examined: -

MBS to be held

If the main engine has not been cared for  
during the lay-up period the H.P. cylinder and  
two main bearings should be opened out and  
examd. Further examine to be left to the discretion  
of the Surveyor. The ballast pump water end,  
subject to renewal by C/S, should be specially  
examd.

all machinery, pumping arrangements  
and electrical equipment to be tried under  
working conditions

Phoned to Gates  
W. R. H.  
16.5.55

Lloyd's Register  
Foundation

002997-003005-0056