

Lloyd's Register of Shipping

UNITED WITH THE BRITISH CORPORATION REGISTER

BRITISH COLUMBIA

1718 MARINE BUILDING
VANCOUVER 1, B.C.

RECEIVED

12th September, 1958.

Classn. (S)

29 SEP 1958

Ans'd

The Secretary,
Lloyd's Register of Shipping,
London.


Dear Sir:-

S.S. "CEDARPOOL"
Vancouver Report 10348

I have to acknowledge receipt of your classing letter dated 8th July and have to advise you that a small welded doubling plate was fitted to a local wasted area on the starboard forward inboard side of the No.7 DB Tank Top.

It is regretted that this item was not mentioned in the body of the report.

Yours faithfully,



SAS/L



© 2020

Lloyd's Register
Foundation

00997-00305-0061

SR

CLASSIFICATION

H M R.f.

Noted 20/11/52
6B52

YOUR REFERENCE

mentioned in the copy of the report.

It is suggested that batteries be fitted

the No. 18 Tank Job.

It is suggested that batteries be fitted to the

small motor launch and also to the

large motor launch and also to the

large motor launch and also to the

RECEIVED
2.2.52

11/12/52

London



© 2020
Lloyd's Register
Foundation

RECEIVED

BRITISH COLONIAL

BRITISH COLONIAL

REGISTERED MAIL FOR BRITISH COLONIAL REGISTRY

ТЕЛЕГРАФСКОЕ УПРАВЛЕНИЕ
ТЕЛЕГРАФСКОЕ УПРАВЛЕНИЕ