

COPY

Ship's name CLAN MURRAY Port Malindi (9 B) No. 4541

Class is subject to Port boiler inboard wing frame Last survey date 2/11/62
being removed by 11/62 (2 months limit).

MBS (dec 2/62) commenced 6/62, NOT advanced.


Repair:

boiler feed check - valves of starboard and center
boiler repaired. Forward main feed pump water end cover repaired.
The Surveyor makes no recommendation and it is not recommended
that the Forward feed pump water end cover be removed by
2/63 (3 months limit).

subject as above and as recommended

To complete the MBS.

Port boiler to be examined
and its 8% adjusted value
subject also to be dealt with.



© 2020

Lloyd's Register
Foundation

001997-003005-0155