

Chief Surveyors

Received from Chief Surveyors

NAMES

"CLARA MONKS"

REPORT

Liv.

No. 150428

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92).

Survey Docking: Minor repairs.

When due

NOTED.

Subject to indented bow plating (p.s.f.) also stem bar specially examined at the next drydocking and dealt with as necessary at the Special Survey.

FREEBOARD SURVEYORS TO NOTE discrepancy between freeboard as reported and as recorded in Register Book.



© 2021

Lloyd's Register
Foundation

003006-003012-0089

28.11.58
C. B. M.