

Received from Chief Ship Surveyor 27 JAN 1959

SHIP'S NAME "CAPTAIN HOBSON" REPORT Bom. No. 12941.

Outstanding Conditions of Class: None.

Endorsement of Certificate (As before or None) ~~XXXXXXXXXX~~

Nature of Present Survey: (Afloat and in dry dock) ~~XXXXXXXXXXXXXXXXXXXX~~


Temporary repairs to casing top plating.

Recommendation: SUBJECT to casing top plating being examined and dealt with as found necessary next drydocking.

As now. Subject.

S.R.L. APPENDIX.

Indented shell plates Nos. 2 in 3rd & 4th below sheer (p.s.f).  
(Pitted shell plating (p & s) to be kept under observation).  
Last examined 5,58.



Lloyd's Register  
Foundation  
22/1/59