

The class is subject to the after main feed pump chamber being specially examined or the chamber renewed on the vessel's arrival at Bombay on completion of the present voyage.

4E

by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

NAME.....JEHANGIR

REPORT.....

Bom


No. 12337.

MBS due 5.57 finally held 5.57 now completed
Docking. Screwshaft seen.

S.R.L. The after main feed pump water end chamber examined and found to remain efficient, and the Surveyor recommends the feed pump water end be renewed at the next Special Survey.

The Owners have isolated the Donkey Boiler by fitting blanks in the steam and water liners and by removing a few pipes, and the Surveyors recommends the Donkey Boiler not being used until surveyed.

MBS IT IS SUBMITTED this vessel is eligible for the record
MBS 5.57, TS (CL) 7.57, subject as now recommended.



del
6.8.57.

© 2020

Lloyd's Register
Foundation