

No. of visits 3.  
Interim Certificate issued

First date 14-8-62.  
Damage not issued

Last date 28-8-62.

1962

COPY

Ship's name "CRONULLA" Port H.Kg No. 17303

There is an S.R.L. Appendix item.

A SPECIAL SURVEY (C) became due 6,62.

The HONG KONG Surveyors report (8,62) ship examined afloat and the Special Survey commenced by the examination of:-

Holds and tween decks,  
Fore Peak tank.

They also state that while the ship was lying at anchor in Harbour on 1.9.62, the ship grounded, turned over and appears to be a total loss.

In view of the above, IT IS SUBMITTED  
ACTION be DEFERRED pending further information.

IN S.R.L. APPENDIX  
Shell plate No. 15 (p.s.f) indented.

P.F.C  
22/11/62



© 2020

Lloyd's Register  
Foundation

003018-003012-0070

S.3

as stated above and on the interim certificate.)

of Committee

Surveyor to Lloyd's Register of Shipping

THURSDAY 29 NOV 1962

POSTING