

COPY.

# Lloyd's Register of Shipping,

united with THE BRITISH CORPORATION REGISTER.

BELONGS TO

ROTTERDAM REPORT No.

44821

Port of ROTTERDAM.

28th January, 1958.

This is to Certify that I have

Port & Stbd. Donkey part

Surveyed the Boiler and Machinery of the m.v. "CASSIAN SEA", 10291 tons gross of Monrovia, whilst lying afloat and placed in drydock at this port on the 31st December, 1957 and subsequently for Condition, Continuous Survey of Engines, Donkey Boiler Survey, Repairs and General Examination

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction, and that I have

Recommended that the record of Continuous Survey of Engines, with date, and Donkey Boiler Survey 1-58

be made in the Register Book in the case of this vessel when

the survey has been completed. subject to M.E. cylinder covers Nos. 1 and 2 to be specially examined by July, 1958 (6 months limit), governor inboard generator to be examined and tested under working conditions by July, 1958 (6 months limit) and propeller to be specially examined and dealt with as found necessary next drydocking.

Parts now examined:—

Main Engine:

Nos. 1-2-3-4-5-6 cylinders, covers, pistons and rods, valves and gears, Nos. 1-2-4-6 connecting rods, top ends with guides, Nos. 4-6-7-8 crankpins and bearings, Nos. 10-9-8-7- journals with bearings.

Independent Stbd. aft S.W. cooling pump.

Port aft ballast pump.

Emergency fire pump.

All fresh water coolers.

Lubricating oil cooler.

Stbd. fwd. independent air compressor.

Port outboard steam prime mover for generator.

Electrical equipment.

Port & Starboard donkey

boilers, exh. gas economiser.

Propeller and outside fastenings.

Engineer Surveyor to Lloyd's Register.


D. Kampman

S. Kampman P.T.O.

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or of its Surveyors, or other Officers or Agents of the Society.

1. (C.S.)



003023-003028-0195

and Casings... yes  
 securing appliances... yes  
 companionways and... yes  
 D.B. Tanks (indicate Oil Fuel and Cofferdams) under cylinders - yes

COPY

Lloyd's Register of Shipping

United with THE BRITISH CORPORATION REGISTER

18821

To complete the Donkey Boiler Survey 1-58 the safety valves of both donkey boilers and exhaust gas boiler remain to be floated under steam, steam smothering, fuel oil units and remote controls to be examined working.

28th January, 1958

This is to Certify that I have

Surveyed the Boiler and Machinery of the S.S. "CORSIAN SEA" 1951 tons gross of tonnage, which is a gas boiler and placed in drydock at this port on the 12th December, 1957 and subsequently for the Donkey Boiler Survey of engines, donkey boiler survey, repairs and general examination.

and that I have transmitted to the Committee of Lloyd's

Register of Shipping, London, a Report stating that all

recommendations made by me in connection therewith have

been carried out to my satisfaction, and that I have

recommended that the records of Donkey Boiler Survey of engines,

with date, and Donkey Boiler Survey 1-58

be made in the Register Book in the case of this vessel when

the survey has been completed.

Parts now examined:—  
 1. 1-2-4-5-6 cylinders, covers, pistons and rods, valves and gear, 1-2-4-6 connecting rods, top ends with guides, 1-2-4-6 crankpins and bearings, 1-2-4-6 journals, 1-2-4-6 cooling pump, 1-2-4-6 ballast pump, 1-2-4-6 emergency stop pump, 1-2-4-6 air filter, 1-2-4-6 air cooler, 1-2-4-6 independent air compressor, 1-2-4-6 steam primer cover for generator, 1-2-4-6 donkey boiler, 1-2-4-6 donkey boiler survey.

Engineer Surveyor to Lloyd's Register  
 J. Langford

While the Committee is pleased to ensure that the functions of the Society are properly executed, it is not responsible for any machinery in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book, or for any error of judgment, default or negligence of any of its Committees or any Member thereof.



© 2021  
 Lloyd's Register  
 Foundation