

Chief Surveyors _____

Received from Chief Surveyors _____

'S NAME

Stl Le M/V "BRUNSWICK"

Report

glo

No. 18952

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.)

f Survey

When due

Rensa Rule

✦ 100 A.L. (Steel) Carrying Petroleum in Bulk

2 Dhs (Stl) & web frames. Longitudinal framing

Cell D.B. u E. 65' 221 t. F.P.T. 218 t. APT 111 t.

F.K. 16 B.M. (11 B.M. to Upper Dh, 5 B.M. to 2nd Dh) pt. am. Lloyds A & CP.

P. 109' F 40' Machy Aft.



© 2020
L.R.

6/9/28

Lloyd's Register
Foundation

003038-003045-0041