

Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....


AME *✓* "DRUPA"REPORT *Singapore*No. *13679*

ABR. due 9/59, not held
 TSEL. due 9/61, not held.


C.S. advanced, Docking, Repairs

All main engine cylinder blocks removed at split screws and false C.T.
 fitted. Main engines and ~~some~~ some auxiliaries overhauled
 repaired as necessary. Main engine NO. 3 and 7 cylinder covers
 seized by metallock and the Surveyor recommends that the
 main engine NOS. 3 and 7 cylinder covers (metallock 12/59) be re-examined
 6/60 (6 months limit).

It is submitted that this
 vessel is eligible for THE
 RECORD ABR. 12/59
 TSEL. 10/59.



Subject is not recommended.



Lloyd's Register
 Foundation

WAC
12/1/60.

003038-003045-0165