

COPY

# LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, Fen, London

Telephone: ROYal 3551 (6 Lines)

17th October, 1957.

sn(S)

Dear Sirs,

## Motorship "GADILA"

A report has been received from the Society's Surveyors at Singapore from which it is noted that seven lengths of chain cable and a bower anchor have been lost.

Seven lengths of chain cable and the spare bower anchor were fitted at this time, however, and the Surveyors have recommended that a bower anchor should be supplied at the earliest opportunity. The Committee have continued the class of this ship subject to this being done, and I shall be glad to learn what arrangements are being made for a bower anchor to be supplied.

Yours faithfully,

c.c.Rot.

Assistant Clerk to the  
Classification Committee.

Messrs. Shell Tankers, N.V.,  
Groothandelsgebouw,  
P.O.Box 874,  
Rotterdam,  
Holland.



© 2020

Lloyd's Register  
Foundation

003046-003055-0249