

REC'D NEW YORK NOV 30 1959

14 DEC 1959

14 DEC 1959

Rpt. 9

Date of writing report 14.11.59

Received London

Port Curacao, N.A.

No. 5822

Survey held at Willemstad, Curacao, N.A.

No. of visits 2

First date 10.11.59

Last date 11.11.59

## REPORT OF PERIODICAL SURVEYS & REPAIRS OF MACHINERY

No. in R.B. 08811 Name M.V. "DORCASIA" Gross tons 8083 Date of build 8-1938

Owners Shell Petroleum Co. Ltd. Managers - Do - Port of Registry London

Engines made 1938 By J. G. Kincaid & Co. Ltd. Type Oil Engine

No. of Main Engines 1 No. of Screws 1 Records of Survey & Special Notations as per Register Book

No. of Main Boilers . . . W.P. . . .

No. of Aux./Donkey Boilers 1 W.P. 180 lbs.

Surveyed Afloat or in Dry Dock Afloat

Nature of Survey CS & Repairs

Was Damage Report issued? Int. Cert.? YES

Last Report (For Head Office only)

Hull		Machinery
+100A1	6,59	CS 5,56
(DR)	5,56	d 6,59
		CL 6,59
		SPS 5,56

The condition of any of the following items is to be described as "good" only when the part has been examined, found or placed in good condition, and is considered to be acceptable until the due date of the next Periodical Examination. Where it is considered that re-examination or repairs should be effected before the due date of the next Periodical Examination a distinguishing mark thus + should be inserted against the item and the circumstances and action recommended described fully under "defects and repairs". At part or complete Special Surveys those items which are not applicable to the ship should be cancelled with a black line; this need not be done when the machinery is on a continuous survey basis. When any part has been subjected to pressure test this should be stated. Engine parts when referred to by numbers should be counted from forward.

DOCKING Propellers Wear Down of Stern Bushes Oil Glands Sea Connections

Fastenings Has Screwshaft Tubeshaft been drawn? Date of Examination Has Shaft been changed?

Has Shaft now fitted been previously used? Has Shaft now examined/fitted a continuous liner? Approved oil gland?

MAIN ENGINES (Recip. Steam or I.C.) PORT STANBORD

1 Cyls., Covers, Pistons & Rods No.8 Good

2 Valves & Gears No.8 Good

3 Connecting Rods, Side Top Ends & Guides Centre

4 Crankpins & Bearings, Side Centre

5 Journals & Bearings

MAIN ENGINE DRIVEN AIR COMPRESSORS

6 Cyls., Covers, Pistons & Rods

7 Connecting Rods & Top Ends

8 Crankpins & Bearings

9 Journals & Bearings

10 Coolers & Safety Devices

MAIN ENGINE DRIVEN SCAVENGE PUMPS

11 Cyls., Covers, Pistons & Rods

12 Connecting Rods & Top Ends

13 Crankpins & Bearings

14 Journals & Bearings

15 Levers

16 SCAVENGE BLOWERS

17 SUPERCHARGERS

MAIN TURBINES

18 Casings, Rotors, Blading, Bearings & Thrusts

19 EXHAUST STEAM TURBINES (WITH RECIP. ENGINES)

20 STEAM COMPRESSORS

21 CLUTCHES & HYDRAULIC COUPLINGS

22 REDUCTION GEARING

23 THRUST BLOCKS, SHAFTS & BEARINGS

24 INTERMEDIATE SHAFTS & BEARINGS

25 HOLDING DOWN BOLTS & CHOCKS

26 CONDENSERS (MAIN & AUX.)

27 STEAM RE-HEATERS

28 DE-SUPERHEATERS

29 STOP & MANOEUVRING VALVES

30 MAIN ENGINE DRIVEN PUMPS

31 CRANKCASE DOORS & EXPLOSION RELIEF DEVICES

Have Main Engines been tested working and manoeuvring?


OPINION OF MACHINERY AND RECOMMENDATIONS

The machinery of this vessel as far as now seen, is in good condition and eligible in my opinion to remain as

classed with fresh record of CS (with date) on completion of the Survey.

Date of Committee THURSDAY 31 DEC 1959

Decision As now



© 2020

(J.C. Nobels)

Engineer Surveyor to Lloyd's Register of Shipping

Lloyd's Register Foundation

0063056-003064-0092

If certificate is required state where to be sent



32 Essential Independent Pumps (Identify by position)
33 Bilge, Ballast & Oil Fuel Suction Lines, Fittings & Controls
34 Have the remaining Piping Arrangements & Fittings in the machinery space been examined as considered necessary?
35 Fresh Water Coolers
36 Lub. Oil Coolers
37 Heaters (state service)
38 Independent Air Compressors, Coolers & Safety Devices
39 Air Receivers & Safety devices—Main
40 Auxiliary
41 Oil Fuel Tanks (Not forming part of hull structure)
42 Evaporators
43 Have Evaporator Safety Valves been tested under steam?
44 Steering Machinery
45 Windlass
46 Fire Extinguishing Arrangements

AUXILIARY ENGINES (Identify by position)

ELECTRICAL EQUIPMENT

PROPULSION PORT STARBOARD AUXILIARY EQUIPMENT
a Generators
b Exciters
c Air Coolers
d Motors
e Air Coolers
f Control Gear, Cables, etc.
g Insulation Resistance
h Insulating Oil Test
i Overspeed Governors
j Magnetic Couplings
k Air Gap
l Generators & Governors
m Motors
n Switchboards & Fittings
o Circuit Breakers
p Cables
q Insulation Resistance
r Steering Gear Generators and Motors
s Navigation Light Indicators

BOILERS OPENED UP & EXAMINED (Identify by position and state latest date of internal examination of each boiler)

MAIN AUXILIARY, DONKEY or PRESS
Superheaters
Safety Valves
Mountings, Doors & Fastenings
Safety Valves Adjusted to Sat. Spt.
Boiler Securing Arrangements
Main Economisers
Exhaust Gas Heated Economisers
Steam Heated Steam Generators
Steam Generator Safety Valves Adjusted to
Were Oil Burning System & Remote Controls examined working in accordance with Rules?
Forced Circulating Pumps
Have Saturated Steam Pipes in cylindrical boiler smoke boxes been examined as required by Rules?
Funnel

EXAMINATION & TESTING OF STEAM PIPES (State material)

Main Auxiliary (over 3 in. bore)
Were Copper Pipes annealed?
Have Saturated Pipes in cylindrical boiler smoke boxes been tested?

PARTICULARS OF DEFECTS & REPAIRS, ETC. (Damage repairs should be detailed separate from wear and tear repairs; state what action has been taken regarding items which are subjects of class)

Wear and Tear Repairs:- M.E. No.8 cylinder cover, liner, jacket, skirt and piston renewed, due to excessive wear.
New parts found marked as follows:-

Cover:- Lloyd's Test 800 lbs. 29.4.38 W.G.M.
Jacket:- Lloyd's Test 50 lbs. 3.5.38 W.G.M.
Liner:- Lloyd's Test 100 lbs. 18.9.57 H.R.T.
Piston:- Lloyd's Test 100 lbs. 2.6.58 H.K.T. No.598/57

C.S. Advanced.
It is submitted that this vessel is eligible to remain as CLASSED.


22-12-59

LEAVE THIS SPACE BLANK

Survey fees Fls.150.00

Damage fee
Expenses... 10.00

Date when A/c rendered 11.11.59



© 2020

Lloyd's Register Foundation