

Class is subject to

4E

✓ H.P. cylinder casting being removed by 6/61 (9 mos. time)

8 2/ Forward boiler not be used until repaired on return to Sydney this voyage.

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

18 MAY 1961

SHIP'S NAME

SS. "CHANCTE"

REPORT

Sydney


No. 33879.

ES due 6/60. (Postponed until 6/61, approved 1/12/60.)
MBS. due 12/60, partly held 12/60,
now advanced.RepairsSRL. Item (2) above, Ford. boiler, dealt with and to be deleted.

It is submitted that the
vessel **WILL BE** eligible
for the record MBS. 12/60
when the survey has been
completed, as per this Rpt (Cont.).

Subject as above re H.P. cylinder
and without condition re Ford.

17/5/61.



© 2020

Lloyd's Register
Foundation

003056-003064-0301