

REPORT on the *S/S Formosa*

The Surveyor should be requested to state the sizes of the hatchways, omitted from the report

GRM

9.2.21



© 2021

Lloyd's Register
Foundation

003065-003074-012